

# HOW TO LOWER THE WAITING POSITION IN KEBA CONTROLLER



HY ROBOTIC

### WARNING

THIS MODIFICATION MAY CAUSE SERIOUS DAMAGE ON THE ROBOT ARM, EOAT, AND THE MOLD MACHINE.



For the safety,

The program requires the Waiting position z-axis to be "0 mm"

However, you can lower the waiting position so that you can save taking-out time.

This modification may cause an accident. Do at your own risk.

### DO NOT FORGET

BACK UP THE MEMORY DATA BEFORE MODIFYING THE FILES



### Log in level 16 Admin PW: pass



At first, the mold safety area need to be adjusted


Press menu button TWICE




### Press here




### Press EUROMAP



### Go to Setting



Go to Teach mold no-go area



### Go to NEXT



#### Default is 100mm


From waiting position,
Move the robot arm down
manually WITH CAUTION
Until the top of the mold
area. See sample pic.



### Then teach And Finish

Adjusting the mold safety area is done.

The next step is modifying the system file.



#### Press here



### Press here



You will see your mold project files




Press + button and Expand currently loaded mold project file



## Find WaitingPosition And OPEN it




Confirm
WaitingPosition is loaded





(1) Scroll down to bottom

2 Select the line
JUST BEFORE
HYWaitMoveIsFinished()



### EDIT – Show Commands



#### Movement - MoveHY



### **Press Modify**



1 from set waiting position
Move the robot arm
to the designated z-position

2 Confirm Rotation

3 Teach and OK





### Kill currently opened WaitingPosition



- 1) Kill currently opened master
  - 2) Open master again

